



March 4, 2024

San Simeon Community Services District  
111 Pico Avenue  
San Simeon, CA 93452

**SUBJECT: FEBRUARY 2024 MONTHLY FACILITY REPORT FOR THE SAN SIMEON COMMUNITY SERVICES DISTRICT WASTEWATER TREATMENT PLANT, WATER SYSTEM, AND COLLECTION SYSTEM**

**WASTEWATER TREATMENT PLANT**

The recent storms have required much more operational effort. The wastewater treatment plant is seeing the amount of inflow triple during rain events which requires more time onsite with operating the plant. The increase is due to stormwater infiltrating the collection system and then flowing to the wastewater treatment plant. FRM Staff is investigating every potential infiltration source to reduce the amount of stormwater inflow.

**WATER SYSTEM**

Staff treated the well water using the filtration system since there was flow in Pico Creek. The recent rainfall has added to the difficulty and the amount of time spent treating the water to potable standards. The filters are changed out regularly along with keeping backup supply onsite. and the new SCADA system is operating and providing the monitoring information and alarming required by the Division of Drinking Water. All drinking water standards are currently being met.

**COMPLIANCE**

- Compliance is working on updating the Hazardous Materials Business Plan.
- FRM completed a routine inspection with the Air Pollution Control Board.
- The District's water and wastewater generators and supporting documentation were reviewed and no deficiencies were found.

Sincerely,

**FLUID RESOURCE MANAGEMENT**

